

TPIC 2019 Update No.1 Errata

Below is a list of the errors contained in TPIC 2019, as published June 2022.

2/1/2023

1. **Table 6.6.2 Truss Deflection Limits**

Change the *Bottom chord truss joint or panel* limits for Floor as follows:

- a) Plaster/Gypsum ceiling VL/360
- b) Other ceiling VL/360
- c) No ceiling VL/360